

ST. JOHN'S AUGUST 2009

Visionotes

Stonework Done!

The window well at the back of the church has been rebuilt per the agreement signed last fall with John Gishnock, owner of Formecology. The repair has completely resolved the motivating factors of safety concerns and damages in the basement area had the wall collapsed. The additional benefit of choosing to make this repair with stone is that it was deemed an aesthetically pleasing resolution that is in harmony with the design of our church. Most recently the missing stone in the top of the wall has been replaced to bring the project to its conclusion.

Thanks to John and his associates for their attention to detail and the beautiful final product. It's great to see fine workmanship from a hometown firm.

